



DESCRIPTION	BY	PROJ. MANAGEF
REVISED PLANS BASED UPON CHAZEN COMMENT LETTER DATED 7/22/21 AND PB MEETING ON 7/27/21	JWE	CHIEF DESIGNE
REVISED PLANS BASED UPON CHAZEN COMMENT LETTER DATED 8/9/21 AND PB MEETING ON 8/10/21	JWE	DESIGNED BY:
REVISED PLANS BASED UPON NYSDOT COMMENT LETTER DATED 11/7/21	JWE	DRAWN BY:
REVISED PLANS BASED UPON NYSDOT COMMENT LETTER DATED 1/25/22	JWE	






(Layout: 7-20-22.dwg plan File/Site -Croton NY/04-Cad Reagan Projects/Other Clients\2021\2021-04E-- 2:26 PM (Name: jeaston) I:\Engineering F Aug 15, 2022 -Name: e: Mon, File N Date:


C-10)

43-45 Maple Street

Two additional trees to be removed.




Tree is 2 feet from retaining wall.



Large root was cut to allow retaining wall to be constructed



Trunk and root zone was damaged during construction of retaining wall



Canopy of tree, communication wire close to tree



Tree is about 6 feet from retaining wall, roots and truck were buried in grading fill



Tree is about 6 feet from retaining wall, roots and truck were buried in grading fill



Canopy of tree

