

FACILITIES DEPARTMENT - PROJECTS SCHEDULED SUMMER 2022

CES	GFS	KHS	LLS	SES	BMS	CMS	SHS
ESC -To complete bms system connection for heating pump COMPLETE	UTILITY COMM . - Interior cameras installation (Antinozzi 2022) IN PROGRESS	FERRARO - Exterior power wash (Antinozzi 2022) COMPLETE	ACCUSPEC - Desicant Dehumidifier for the school COMPLETE	GREENWOOD INDUSTRIES - Roof replacement IN PROGRESS	ToW - Parking lot repavement COMPLETE	CHERRY HILL GLASS - Broken window replacement IN PROGRESS	TRINITY CONSTRUCTION - Window sealing to prevent water penetration IN PROGRESS
ITS - PA System upgrade due to age (Antinozzi 2022) IN PROGRESS	ORANGE FENCE - Exterior fence repair (car accident) COMPLETE	FERRARO - Exterior dumpster gates to be painted (Antinozzi 2022) COMPLETE	DALENE FLOORING - Gym floor maintenance COMPLETE	ITS - Clock system upgrade to wireless GPS COMPLETE	BoE - Challenge course Installation, (Outdoors) SCHEDULED	CSC - Kitchen hood cleaning COMPLETE	ToW - Parking lot repavement near by the pool and driveway only COMPLETE
ESC/HVAC - Unit ventilators installation room 2,3 IN PROGRESS	CSC - Kitchen hood cleaning COMPLETE	INTERNAL - Room 10 water leak repair (lead paint) COMPLETE	CSC - Kitchen hood cleaning COMPLETE	CAPASSO - Masonry repairs by door # 2, repair concrete stairs by door #25, repair concrete steps by loading dock area COMPLETE	TRINITY CONSTRUCTION - Insulated glass window sealing to prevent water leak IN PROGRESS	UTILITY COMMUNICATIONS - (7) new walkie talkies IN PROGRESS	CSC - Kitchen hood cleaning COMPLETE
FERRARO - Exterior canopy painting (Main entrance) COMPLETE	PRO-TURF - Fiber mulch, playground COMPLETE	RAMOS CONST. - Installation playground equipment SCHEDULED	WESTPORT F.D. -Fire Code violations inspections COMPLETE	CSC - Kitchen hood cleaning COMPLETE	CSC - Kitchen hood cleaning COMPLETE	WESTPORT F.D. -Fire Code violations inspections IN PROGRESS	CUSTOM AQUATICS - Commercial chemical feed system IN PROGRESS
ARIES MODULARS - Installation modular classrooms project IN PROGRESS	WESTPORT F.D. -Fire Code violations inspections COMPLETE	RED TECHNOLOGIES - Underground oil tank removal COMPLETE	CIRMA- Playgrounds Inspections COMPLETE	WESTPORT F.D. -Fire Code violations inspections COMPLETE	WESTPORT F.D. -Fire Code violations inspections COMPLETE	CIRMA- Playgrounds Inspections COMPLETE	NORTHEAST GENERATOR - Generator JO repair and PM COMPLETE
FPT- 5 Year Hydrostatic test COMPLETE	CIRMA- Playgrounds Inspections COMPLETE	CSC - Kitchen hood cleaning COMPLETE	WILLCO DOORS -Preventative Maintenance, operable walls COMPLETE	CIRMA- Playgrounds Inspections COMPLETE	CIRMA- Playgrounds Inspections COMPLETE	WILLCO DOORS -Preventative Maintenance, operable walls COMPLETE	ETT - Oil tank concrete pad replacement, JO tank, by the pool parking lot COMPLETE
CSC - Kitchen hood cleaning COMPLETE	WILLCO DOORS -Preventative Maintenance, operable walls COMPLETE	WESTPORT F.D. -Fire Code violations inspections COMPLETE	FERRARO - Interior classrooms painting COMPLETE	WILLCO DOORS -Preventative Maintenance, operable walls COMPLETE	WILLCO DOORS -Preventative Maintenance, operable walls IN PROGRESS	PLOURDE PAINTING, Interior painting, stairwells handrail COMPLETE	WESTPORT F.D. -Fire Code violations inspections COMPLETE
MULTIPLE VENDORS - Modular classroom installation project IN PROGRESS	NORTH HAVEN TILE - VCT tile replacement room 231 COMPLETE	CIRMA- Playgrounds Inspections COMPLETE	PRO-TURF - Fiber mulch, playground COMPLETE	FERRARO - Interior / exterior painting, multiple areas COMPLETE	FERRARO - Interior painting, multiple areas COMPLETE	BoE - Challenge course Installation, (Outdoors) IN PROGRESS	CIRMA- Playgrounds Inspections COMPLETE
WESTPORT F.D. -Fire Code violations inspections COMPLETE	FERRARO - Interior painting, multiple areas COMPLETE	PRO-TURF - Fiber mulch, playground COMPLETE		NORTH HAVEN TILE - Carpet rip up and VCT installation, rooms 174, 183 COMPLETE	TRANE, Replacing Chillgard LE Refrigerant monitor IN PROGRESS	ARROW LINE, Fire lines, arrows and crosswalks repaint. SCHEDULED	WILLCO DOORS -Preventative Maintenance, operable walls COMPLETE
CIRMA- Playgrounds Inspections COMPLETE	NORTHEASTERN COMM. - Cabling installation for interior cameras COMPLETE	FERRARO, Interior, Exterior painting, multiple areas COMPLETE		PRO-TURF - Fiber mulch, playground COMPLETE			MECHANICAL SOLUTIONS - JO pump repair (Tom Carr) IN PROGRESS
UNITED SEWER -Main Line cleared SCHEDULED		RD WEISS - Main stairs treads replacement SCHEDULED		ARROW LINE, Fire lines, arrows and crosswalks repaint. SCHEDULED			PLOURDE PAINTING, Interior painting, columns in cafeteria COMPLETE
FERRARO, Interior Painting, multiple rooms, 437 acc. COMPLETE		ARROW LINE, Fire lines, arrows and crosswalks repaint. SCHEDULED					BoE, Challenge Course Installation (Outdoors) IN PROGRESS
ARROW LINE, Exterior graphics painting, blacktop SCHEDULED							PRO-TURF - Fiber mulch, Little Wreckers playground COMPLETE
WILLCO DOORS -Preventative Maintenance, operable walls COMPLETE							ARROW LINE, Fire lines, arrows and crosswalks repaint. SCHEDULED
PRO-TURF - Fiber mulch, playground COMPLETE							
UTILITY COMMUNICATIONS - (6) new walkie talkies IN PROGRESS							